


SmartSignal Predictive Analytics – OSIsoft Anchorage Regional Seminar

**Nick Perkins – Solution
Architect – September 16, 2010**

What Happened to Nick?



Goal: Operate Safely – while meeting Production & Profit Targets ...



- Increasing equipment availability
- Preventing unsafe situations
- Beating financial expectations

Data Rich, But Information Poor?

**3 Months Early
Warning of Booster
Compressor Fouling**



Agenda

- Overview of SmartSignal
- How the Technology Works
- Examples from BP Alaska

Benefits

➤ **Avoid Surprises**




➤ **Reduce Production Losses**



➤ **Reduce Risk of Recordable Incidents**

395 days
without a
recordable incident

Any Equipment, Any OEM



Client Success:

New Markets, Adapting to Their Needs, Results Achieved



- Halved mid-air events
- \$1.5M annual maintenance reduction
- \$millions in avoided/reduced engine failures

8yrs



- Central monitoring of entire fleet
- \$millions annually, in routine catches

6



- \$M in documented catches

4



- 975 Wind Turbines
- Substantial catches

Leader in Predictive Analytics



BP Deployments



Upstream:

- Prudhoe Bay, Alaska
- Gulf of Mexico
- North Sea
- **Alternative Energy:** SilverStar wind farm (24 wind turbines)

Refining

- Global license with rollout on critical equipment
 - 2+ Year, comprehensive evaluation and pilots at multiple sites
 - Initial trials generated >\$5 MM in measurable benefits
 - Deployed in 5 refineries



BP Alaska

☞ Deployed on 102 large rotators

☞ Includes:

- Gas Turbines
 - GE Frames
 - GE Aero Derivatives
 - Solar
 - Rolls Royce
 - Ruston
- Centrifugal Compressors
- Pumps
- Generators
- Motors
- Gearboxes

SmartSignal Covers a Range of E&P Processes and Equipment



Rotating Equipment

- ☞ **Engines**
 - Gas turbine
 - Reciprocating
- ☞ **Compressors**
 - Reciprocating
 - Centrifugal
 - Axial flow
 - Screw
- ☞ **Centrifugal Pumps**
 - Single or multi-stage
 - Various seal flush plans
- ☞ **Turbines**
 - Steam turbines
 - Power recovery turbines
- ☞ **Generators**
- ☞ **Auxiliary systems**

Processing Equipment

- ☞ **Gas-Liquid Contact**
 - Glycol Dehydration
 - Amine Sweetening
- ☞ **Heat exchangers**
- ☞ **Separators / Scrubbers**
- ☞ **Boilers**
- ☞ **Waste heat recovery systems**
- ☞ **Fired heaters**

Examples of Early Warnings


Equipment	Examples of Failure Modes
All Rotating Equipment	Bearing and Lubrication Degradation
Gas Turbine Engine	Fuel Nozzle Plugging; Compressor Fouling, Blade Failure, Combustion Liner Deterioration
Internal Combustion Engine	Detonation; Spark Plug Failure, Valve Problems, Performance
Centrifugal Compressor	Rotor Fouling, Seal Degradation, Performance
Reciprocating Compressor	Valve Problems, Rod Drop, Rider Band Wear, Performance
Centrifugal Pump	Cavitation, Performance, Seal Degradation
Suction Scrubber	Liquid Carryover; Demister Pad Plugging
Heat Exchanger	Fouling; Tube Leaks
Gas Treating	Solvent Carryover; Absorber / Stripper Flooding, Glycol Carryover
Power Generator	Stator Temperature Excursion, Rotor Problems

Utilizes Existing Instrumentation, Controls, and Data Infrastructure


Any oil and gas equipment

Process network

Business network




How SmartSignal Works



Conventional Monitoring

- Most conventional monitoring methods use threshold limits on each sensor
- Levels chosen must cover all operational ranges and be applicable for all ambient conditions
- Traditional monitoring techniques are limited in their ability to identify failures proactively




SmartSignal Approach


Enabled by Modeling Related Sensors



Stand-alone equipment protection



The Model



1	2	3	4	5
Gas turbine compressor section: Performance model	Load compressor: Performance model	Gas turbine combustion/exhaust: Performance model	Rotor dynamics & auxiliaries: Mechanical model	Waste heat recovery or emissions: Performance model



smart**signal.** 

Examples from BP Alaska


GC2 P7704B Pump – July 2008

Notification – to BP Reliability Group




48.7541, 7/15/2008 6:00:00 PM

(PUMP_SPEED) - HIC-02-T5106, SULZER P7704B MANUAL SPEED, %




40.3600, 7/15/2008 7:10:00 PM

(SUCTION_FLOW_1) - F01-02-T506, SULZER P7704B MINFLO TOTAL, BBL/S



1,934.3200, 7/15/2008 1:50:00 PM

(DISCHARGE_PRESSURE) - P1-02-T510, SULZER P7704B PUMP DISCHG, PSIG



➤ Pump operating at or near minimum flow, low discharge pressure and high speed

➤ Recommendation: Check field for filter plugging or obstructions.

GC2 P-7704B Pump – Action Summary



- Reliability Engineer started investigation with field Reliability Tech
- Believed there may be a problem with the pump bundle
- Upcoming S/D, so Overhaul ordered a complete pump bundle to have on standby
- On the scheduled S/D, 5 minute boroscope inspection revealed significant wear / damage
- Based on the condition of the bundle, it was changed out, minimized production impact

FS2 – 1802 Inboard Seal Issue

BP Exploration Alaska SmartSignal Monitoring Report

5/17/2010

smartsignal.

Availability & Performance Center

FS2
FS2 16-1802
Possible seal issue

Status: 01) Notification to Customer

Date of Notification: 5/17/2010
12:00:00 AM


Equipment Tag: Outboard seal temperature
Category:

Description:
Seal temperature spiking following a step change


Diagnosis:
Possible seal issue

Customer Response:

FS2:1613-T192L.PV, STV COMP-OUTBRD OUTE R SEAL TEMP. (DEG F)



FS2:1613-T191L.PV, STV COMP-OUTBRD INNE R SEAL TEMP. (DEG F)



Gas Camera Results



Questions?



Nick Perkins

nperkins@smartsignal.com

Phone 630.829.3230

FS3 14-15188

BP Exploration Alaska SmartSignal Monitoring Report

9/14/2010

smartsignal.

Availability & Performance Center

FS3

FS3 14-15188

Report 579 -Update- Gen axial
position - positive residuals

Issue Tracking Number: 579

Status: 01) Notification to Customer

Date of Notification: 6/23/2010 12:00:00 AM

Equipment Tag: 1441-X8106L

Category:

Description:

Shifted back up to previous reading
Shift in position from 39 to 21 was moore card
changed is this the new condition


Diagnosis:

Possible moore card failure again
Bad or damaged instrument.

Customer Response:

. It is likely that this issue is due to problems
with the Moore card system work order to
repair
What I get out of the email from John (vibe
tech) is that this may be a Moore card issue
that is causing the 39 mil axial reading on FS3
15188. Sounds like it should be reading about
8 mils.

FS3:1441-X8106L PV, 15188 GAS GEN AXIAL POSITION (MILS)



GC2 02-7000



BP Exploration Alaska SmartSignal Monitoring Report

9/14/2010



Availability & Performance Center

GC2
GC2 02-7000
Report 640-Update-
Ambient temperature - bad
sensor


Issue Tracking Number: 640
Status: 01) Notification to Customer
Date of Notification: 8/3/2010
12:00:00 AM
Equipment Tag: TI-01-0001.PV
Category:

Description:
The ambient temperature tag has
stopped retuning data

Diagnosis:
Sensor/data issue

Customer Response:

GC2-TI-01-0001.PV, AMBIENT TEMPERATURE, (DEG F)



FS3 14-1801

BP Exploration Alaska SmartSignal Monitoring Report

9/14/2010

smartsignal

Availability & Performance Center

FS3

FS3 14-1801

Report 653-Update-Comp seal
outboard flood temp - positive
residuals

Issue Tracking Number: 653

Status: 01) Notification to Customer

Date of Notification: 8/17/2010 12:00:00 AM

Equipment Tag: 1412-T209L.PV

Category:

Description:

Condition continues axial position indicating
surging causing temperatures to swing,
Working on a detailed report on this issue
Since starting back up the compressor seal
outboard flood temperature has increased from
190 degF to 235 degF. We have seen a drop in
the seal outboard sweet temperature. Shift in
compressor since the trip and restart on 8/4,
Data feed issue at FS3 at time of report being
worked

Diagnosis:

Possible flow control issue
possible seal issue , seal hanging up, surging
causing temperatures to swing Check outboard
flood TI runing around 235

Customer Response:

FS3:1412-T209L.PV, 1801 IP COMP SEAL OUTBOARD FLOOD TEMP, (DEG F)



ASSET MECHANICAL TAG 32

FS3:1412-T210L.PV, 1801 IP COMP SEAL OUTBOARD SWEET TEMP, (DEG F)




FS3:1412-T209L.PV, 1801 IP COMP SEAL OUTBOARD FLOOD TEMP, (DEG F)



ASSET MECHANICAL TAG 32

FS3:1412-T210L.PV, 1801 IP COMP SEAL OUTBOARD SWEET TEMP, (DEG F)



CCP 18-1810

BP Exploration Alaska SmartSignal Monitoring Report

9/14/2010

smartsignal

Availability & Performance Center

CCP

CCP 18-1810

Report-676-Update-Low speed
gear inboard journal temp -
positive residuals

Issue Tracking Number: 676

Status: 01) Notification to Customer

Date of Notification: 8/17/2010 12:00:00
AM

Equipment Tag: CCP:1839-T75L.PV

Category:

Description:


Up to a 40 degree spread across
bearings when machine is down
additional chart next slide We are
seeing the inboard journal bearing
temperature approximately 20 degF
above model predictions. We have
not seen an increase in the low
speed outboard journal temperature.

Diagnosis:

Data issue moore cards Possible bearing
issue
Possibly increase lube oil pressure


Customer Response:

MODE_RULE_TAG-CCP:1822-S74L.PV, TURB IIP SHFT SPEED IN RPM, (RPM)



DRIVER MECHANICAL TAG 14

CCP:1839-T48L.PV, T48E LUBE TEMP TURB HDR, (DEG F)



ASSET MECHANICAL TAG 2

CCP:1839-T82L.PV, COMP INBOARD JOURNAL TEMP, (DEG F)




ASSET MECHANICAL TAG 4

CCP:1839-T83L.PV, COMP THRUST BRG TEMP, (DEG F)




CCP 18-1810 (cont)



CCP 18-1804

BP Exploration Alaska SmartSignal Monitoring Report

9/14/2010



FS1 15-1802

BP Exploration Alaska SmartSignal Monitoring Report

9/14/2010

smartsignal.

Availability & Performance Center

FS1

FS1 15-1802

Report-685-Update-
Outboard outer seal
temperature - positive
residuals

Issue Tracking Number: 685

Status: 01) Notification to Customer

Date of Notification: 8/31/2010
12:00:00 AM

Equipment Tag: 1513T210L

Category:

Description:

Condition continues


On 8/27 the outer seal temperature increased from 148 degF to 194 degF with spike to 205. We did not see any changes in the outboard inner seal temperature, or other seal temperatures

Diagnosis:

Possible seal flush restriction or sensor issue

Customer Response:

FS1:1513T210L.PV, IP COMP-OUTBRD OUTER SEAL TEMP. (DEG F)



FS1 15-1804

BP Exploration Alaska SmartSignal Monitoring Report

9/14/2010

smartsignal.

Availability & Performance Center

FS1

FS1 15-1804

Report-Update-689-shaft 2
bearing vibrations

Issue Tracking Number: 689

Status: 01) Notification to Customer

Date of Notification: 8/31/2010
12:00:00 AM

Equipment Tag: fs1:97X178I.PV

Category:

Description:


Condition has improved with
decreased speed
There is increased bearing vibrations
with constant turbine shaft speed
starting on 8/29.

Diagnosis:

Possible bearing issue

Customer Response:

FS1:97S39AI.PV, 1804 Turbine LP Shaft Speed, (RPM)



DRIVER MECHANICAL TAG 15

FS1:97X178I.PV, 1804 LP Shaft #2 bearing radial Vert, (MILS)



DRIVER MECHANICAL TAG 16

FS1:97X176I.PV, 1804 LP Shaft #2 bearing radial Horz, (MILS)



CCP 18-1812

BP Exploration Alaska SmartSignal Monitoring Report

9/14/2010

smartsignal.

Availability & Performance Center

CCP

CCP 18-1812

Report-700-Outboard
journal bearing temp
spiking

Issue Tracking Number: 700

Status: 01) Notification to Customer

Date of Notification: 9/13/2010
12:00:00 AM

Equipment Tag: Low speed gear
outboard journal temp

Category:

Description:


Temperature was spiking at this time it
has steading out possibly a conection
issue will add to sensor list

Diagnosis:

Sensor issue

Customer Response:

CCP:1859-T76L.PV, LOWSPEED GEAR OUTBOARD JOURNAL TEMP, (DEG F)



CCP 18-1812

BP Exploration Alaska SmartSignal Monitoring Report

9/14/2010

smartsignal.

Availability & Performance Center

CCP
CCP 18-1803
Report-705-TURBINE
INBOARD HORIZONTAL
VIB - Low residuals


Issue Tracking Number: 705
Status: 01) Notification to Customer
Date of Notification: 9/14/2010
12:00:00 AM
Equipment Tag: CCP:1854-
X168L.PV
Category:

Description:
Since 8/29 inboard horizontal vibration reading has been shifted lower from tracking accurately around 2.3 Mils down to 1.4 Mils (on 9/14). It also appear that on 9/9 reading dropped down to 0.02 Mils.


Diagnosis:
Possible moore card issue

Customer Response:

CCP:1816-S74L.PV, TURBINE HP SHAFT SPEED IN RPM, (RPM)



CCP:1854-X168L.PV, X168E TURB INBOARD HORIZONTAL VIB, (MILS)



CCP:1854-X169L.PV, X169E TURBINE INBOARD VERTICAL VIB, (MILS)

