PETRONAS Rotating Equipment Analytics Enhancement and Scale Up





Presentation Outline

01

MALAYSIA AT A GLANCE

02

ABOUT PETRONAS

03

WHAT IS PROTEAN

04

SOLUTION ARCHITECTURE

05

PROTEAN FEATURES

06

ACHIEVEMENTS

07


SUCCESS STORIES

08

QUESTION AND ANSWER



Malaysia at a Glance





About PETRONAS






*Source: PETRONAS Annual Report 2018



An online remote monitoring system and predictive maintenance solution for rotating equipment



- Uses existing OSIsoft PI data from remote facilities.
- The data will be analyzed within PI AF software suite running various analytics.
- It detects anomaly at incipient stage and subsequently alert the user for any changes and potential threat to the machine.
























Email Alert Notification & Analytics Report

Event: C1 - Comp-C&M 2019-04-15 18:08:00:000

Name: C1 - Comp-C&M Server: VCENPDTPIAFPS01 Database: PROTEAN

Start Time: 15-Apr-19 06:08:00 PM

Target: SKO\BARAM\BAKP\Compressor\K7100\C1 - Comp-C&M

Severity: None

Send Time: 17-Apr-19 02:19:04 PM

Dear All,

Alert triggered for Criticality 1 - C1 - Comp-C&M-Pressure Sensor as below:

No	Name	Fault Code	Operating Value	Low Limit	High Limit
1.	C1_DISC_P1	Normal	7.228357	5.144	8.444
2.	C1_SUCT_P1	High Limit	2.169698	1.175	2
3.	C2_DISC_P1	Normal	11.52411	5.875157	12.17031
4.	C2_SUCT_P1	Normal	6.910936	5.051562	10.80156

Alert triggered for Criticality 1 - C1 - Comp-C&M-Temp Sensor as below:

N	Name	Fault Code	Operating Value	Low Limit	High Limit
1.	C1_DISC_T1	Normal	105.9989	76.68771	131.8907
2.	C3_SUCT_P	Normal	96.1365	65.4474	122.0313

Alert triggered for Criticality 1 - C1 - Comp-C&M-Sensor as below:

No	Name	Fault Code	Operating Value	Low Limit	High Limit
1.	C3_DISC_T	Normal	98.0059	57.59375	105.9187
2.	C3_DISC_P	Normal	24.92554	0.106876	25.326
3.	C3_SUCT_P	Normal	11.077	0.5204459	11.24899


Check for below hyperlink for details: Event Details Hyperlink

Thank You & Best Regards,

PI UPSTREAM SUPPORT Group Technical Data Project Delivery & Technology PETRONAS

PROTEAN										Re	
Informa	tion						elihos				TBA
Notification Number	PMA/A	ngsi/A7500/1	85				ment			\perp	Gas Turbines
Date Region	27	PMA PMA	\rightarrow			Mainto	ubunit			+	Lubrication System Temperature Control
Field		Anzsi					everity			+	Medium
Platform		Angsi					n Requ				To continue monitor
Unit		A7500	_	_	_		ued b			-	Hj Khairul, Harris, Ikram
PROTEAN TAG Description	C2-G1	Lube-Senso	,	_	_	PROTE				+	SPLY_LUBE_T
			-			riptio					
I near to trip setpoint of 71 deg C. Previous	ly during norma	4 generators	operation, this	ature o	of A750 er temp	0 are at	highe was	er side, already	current rea at high sid	but wi	56.5 deg C which already above the alarm of 59 deg C th the current additional load, the temperature has abilitied and maintain at current temperature.
PC\$B Angsi-A Platform			Alarm	and Tri	ip Metri	ix					As-Built
No. DESCRIPTION	RRESI DEVICE	CUSTOMER	RANGE & UNITS			ALAKS	A TRE	NFORM	ATION		MOTES-COMMENTS REV.
MAN LUBE OIL SYSTEM		P721A		ALM	10	15	LL	L	H 191	Type	
1 P70 Libe OI Supply Pressure A 2 P70 Libe OI Supply Pressure B	63076	P731A P731B	0 - 700 kPa			ALM			\rightarrow		
3 P70 Lube Oil Supply Pressure LSS	600P		0 - 700 kPa			504	140	275	-	000	Sec SF SD.
5 Gear/Gen Lube Oil Supply Pressure A	6300A	PTEIA	0 - 345 kPa			ALM					
6 Dearroen Lube Oil Supply Pressure B 7 Dearroen Lube Oil Supply Pressure LSS	6303	P7418	0 - 345 kPa 0 - 345 kPa			ALM SOL	140	100	=	004	2002 SF 5DL
1			0.00000				1.47	177			
9 Main Lube Oil Supply Temperature	2000	T\$41	RTD/*C			ALM			69 71 (165) (160	SON	3
						porti					
(20) 1.23 A PM	30 25	40	7.00 days ≪ 1							*	THE SECRET AND THE SE
50011 2 2 2 PM		49	7.00 days ◀1		Act	tion F	lequ			·	27 MB DEC MO MISSES A TOP ATSOCREMAPINOUT TO MB DEC MO MISSES A TOP ATSOCREMAPINOUT END MB EN
Not Flood Income to Description of Security		40	700 days •		Act	tion F	lequ	nired SAP W	•		27 MB DEC MO MISSES A TOP ATSOCREMAPINOUT TO MB DEC MO MISSES A TOP ATSOCREMAPINOUT END MB EN
Heat Fareaud Intervention Date Doors up the intervention Part		10	7.00 days • 1		Act	tion F	Requ		0		27 MB DEC MO MISSES A TOP ATSOCREMAPINOUT TO MB DEC MO MISSES A TOP ATSOCREMAPINOUT END MB EN
Description of Intervention 1. To continue monitor the header temp	arature.	40			· Con:	seque	ence	SAP W	no Actio		TO A
Description of Intervention 1. To continue monitor the header temp	arature.	40 40 we the hear fi			· Con:	seque	ence	SAP W	no Actio		27 MB DEC MO MISSES A TOP ATSOCREMAPINOUT TO MB DEC MO MISSES A TOP ATSOCREMAPINOUT END MB EN
Devirupion of Intervention. 1. To continue monitor the header temporary to the second of the form of supply temporature one of the for bearing temporature.	arature.	40 40 vs the hear fi	nom the rusnin	gmach	· Con:	sequi	ence L High	SAP VI	no Actio		TO A
Description of intervention 1. To continue monitor the header temp 1. To continue monitor the header temp 1. To continue monitor the header temp 1. To continue monitor the form th	arature.	40 40 to the head fi	nom the rusnin	gmach	· Con:	sequi	ence L High	SAP VI	no Actio		TO A

PROTEAN Solution Architecture





Protean Capability in 2017 (London)



Simple check mechanism



High/low limits on analog values



Follow simple abstraction



Automatic email notification

Current Protean Capability & Features



Simple check mechanism



High/low limits on analog values



A distributed architecture maximizes staff availability



Ability to deal with large amount of data



Management of diagnostics



Follow simple abstraction



Automatic email notification



Reporting of alarm and machine status




Gradient checker/
Deviation



Additional support tools to identify faults

What we have achieved so far







Success Stories





Success Story #1: Safety – Eliminate Fire Hazard

CHALLENGES


- Abnormal rate of lube consumption - Lube oil tank level drop triggered alert.
- Operator top-up the lube oil without investigating the cause of leak.

SOLUTION

- Deviation limit triggered and PROTEAN alert notification issued.
- Inspection done and found lube oil leak.
- Unit shutdown and rectified.

BENEFITS

- Lube oil leak may cause fire (hot surfaces of gas turbine engine and exhaust). Early detection of anomaly and timely intervention had prevented potential fire.
- Cost Avoidance: Equipment damage due to fire.



Insight

Lube oil leak inside Gas
Turbine Enclosure

Success Story #2: Prevention of Platform Shutdown

CHALLENGES

- Instrument air header pressure dropped significantly
- Operator did not notice as the reading was within DCS alarm limit

SOLUTION

- Alert limit triggered.
- PROTEAN alert notification sent to site Operation team.
- Troubleshoot and resolved the issue.

BENEFITS

- Early detection of anomaly and timely intervention had prevented total platform shutdown
- Cost Avoidance: 2 days of major production deferment and excessive value leakage (gas flaring)



Insight

Severe leaking of instrument air supply

Success Story #3: Prevention of Gas Turbine Catastrophic Failure

CHALLENGES


 Fuel gas temperature dropped below dew point during Storm Pabuk affecting two (2) gas turbine engines at an offshore platform in South China Sea

SOLUTION

- Deviation limits triggered and PROTEAN alert notification sent to site Operation team.
- Adjustment made to the superheater firing setpoint.

BENEFITS

- Early detection of anomaly and timely intervention prevent permanent damage and catastrophic failure of the gas turbine combustor liner.
- Cost avoidance: Gas Turbine engine repair and 10 days of gas production curtailment



Insight

Superheater performance degraded realized during low ambient temperature during storm

Success Story #4: Prevention of Gas Compressor Prolonged Downtime

CHALLENGES


- Gas compressor running exceeded rated capacity during high gas demand
- Operating at higher compressor vibration levels exceeded OEM alarm

SOLUTION

- Alert limit triggered and PROTEAN alert notification sent to site Operation team.
- Troubleshoot and resolved issue.

BENEFITS

- Early detection of anomalies triggered detail vibration diagnostic requirement to understand the vibration behavior and its impact during high gas demand (flow). Requirement to run three (3) instead of two (2) trains.
- Cost avoidance: Compressor internal component damage and 14 days production deferment.



Insight

Changes in Operating
Philosophy is required
during high gas
demand

Success Story #5: Detect Small & Fix Small – Lube Filter Clogged

CHALLENGES


Aero derivative Gas
 Turbine engine lube oil
 filters experienced
 frequent clogging.

SOLUTION

- Alert limit triggered and PROTEAN alert notification sent to site Operation team.
- Switched to standby filter (duplex system) online without unit shutdown.

BENEFITS

- Proved that frequent high filter dP was not normal. It indicates the lube was contaminated and prolong running will lead to component damage and catastrophic failure.
- Cost avoidance: 6 hours unplanned production deferment (unit trip) and potential prolonged downtime




Speakers

Khairul Anwar Mohd Nor

- Lead Engineer, Rotating Equipment
- PETRONAS
- khairaw@petronas.com

Musreen Azwan Mustafa

- Manager, Asset Integrity Data
- PETRONAS
- musreen_azwan@petronas.com





Questions?

Please wait for the **microphone**

State your name & company

Please remember to...

Complete Survey!

Navigate to this session in mobile agenda for survey





KEA LEBOHA DANKON

KÖSZÖNÖM БЛАГОДАРЯ

ТИ БЛАГОДАРАМ $\stackrel{>}{\xi}$ TAK DANKE \$\frac{1}{2}\$

HATUR NUHUN

OSIsoft. ESKERRIK ASKO

TEŞEKKÜR EDERIM

GRATIAS TIBI ΕΥΧΑΡΙΣΤΩ **DANK JE** AČIŪ SALAMAT MAHALO IĀ 'OE TAKK SKAL DU HA

GRAZZI PAKKA PÉR PAXMAT CAFA

ДЗЯКУЙ

ХВАЛА ВАМ

MULŢUMESC

ĎAKUJEM

MATUR NUWUN

ありがとうございました
SIPAS JI WERE TERIMA KASIH
UA TSAUG RAU KOJ
ТИ БЛАГОДАРАМ
СИПОС